

FACILITY COMPLIANCE AUDIT REPORT Division of Waste Management Solid Waste Section

UNIT	TY	PE:					
Lined MSWLF		LCID	YW	Transfer	Compost	SLAS	COUNTY: Yadkin
Closed MSWLF	X	HHW	White goods	Incin	T&P	FIRM	PERMIT NO.: 99-02 Closed MSWLF
CDLF		Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO	SDTF	 FILE TYPE: COMPLIANCE

Date of Audit: May 13, 2009 Date of Last Audit: October 31, 2008

FACILITY NAME AND ADDRESS:

Yadkin County Closed Municipal Solid Waste Landfill Landfill Road Yadkinville, NC 27055

GPS COORDINATES: N: 36.1804 **E**: -80.6403

FACILITY CONTACT NAME AND PHONE NUMBER:

Cheri W. Cranfill, Solid Waste Director

w: 336-679-6348 c: 336-469-0125 f: 336-679-2443

ccranfill@yadkincountync.gov

FACILITY CONTACT ADDRESS:

PO Box 1298

Yadkinville, NC 27055

AUDIT PARTICIPANTS:

John Patrone, NCDENR – Solid Waste Section (SWS) Cheri Cranfill, Yadkin County, Solid Waste Director

STATUS OF PERMIT:

Closed

PURPOSE OF AUDIT:

Post Closure Audit

NOTICE OF VIOLATION(S):

None

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. For the violation(s) noted here, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

STATUS OF PAST NOTED VIOLATIONS:

None

FACILITY COMPLIANCE AUDIT REPORT

Division of Waste Management Solid Waste Section

Page 2 of 2

AREAS OF CONCERN AND COMMENTS:

On May 13, 2009, John Patrone met with Cheri Cranfill and conducted a post closure audit of the Yadkin County Closed Municipal Solid Waste Landfill located at Landfill Road in Yadkinville, Yadkin County.

- 1. The facility ceased daily operations on March 30, 1994.
- The landfill cap is covered with native vegetation. 2.
- The facility must ensure that vegetative matter atop the cap and along the slopes is routinely mowed. Woody 3. vegetation should not take-root atop the landfill cap and must be removed.
- 4. Ground water monitoring records were verified. Semi-annual ground water monitoring was conducted in February 2009 and August 2008.
- Water monitoring wells are secured with a lock, labeled, and contain a cement pad. 5.
- Ensure that the facility conducts methane monitoring. See enclosed "Post Closure Conditions," dated September 7, 6. 1995.
- There was no indication of runoff or erosion. 7.

Please contact me if you have any questions or concerns regarding this audit report.

n Patrone

vironmental Senior Specialist

Regional Representative

Phone: 336-771-5095 Fax: 336-771-4631

enclosure

Delivered on : May 19, 2009 by	Hand delivery	x	US Mail		Certified No. [_]
<u> </u>	 		<u> </u>	Ь	

Mark Poindexter, Field Operations Branch Supervisor cc:

Jason Watkins, Central Regional Supervisor

Donald Herndon, Compliance Officer